

## Adam A Bracero

---

**From:** Alfred R Nobrega  
**Sent:** Thursday, May 30, 2013 3:33 PM  
**To:** Adam A Bracero  
**Subject:** RE: DR 10249

Yes and it works. Fred

---

**From:** Adam A Bracero  
**Sent:** Thursday, May 30, 2013 3:33 PM  
**To:** Alfred R Nobrega  
**Subject:** DR 10249

Hey Fred,

I'm looking at this DR that was written for the 11T Winding Traveler. It mentions that a piece of string became caught in the insulating machine and the proposed corrective action said a device would be added to knock off string in the future.

Has this device been implemented?

Link to DR for your reference:

<https://vector-on-site.fnal.gov/Tools/DiscrepancyReport/DisplayDiscrepancyReportReadOnly.asp?qsDRNo=10249>

Adam A. Bracero  
*Manufacturing Process/Quality Engineer*  
*Quality Assurance Representative for Technical Division*

Fermi National Accelerator Laboratory  
PO Box 500, MS 314  
Batavia, IL 60510-5011

(630) 840-2536